




SONY



Error Rate Data

Node	Channel 1			
	L1	L2	R1	R2
20M FB Video	-3.5	-3.5	-3.5	-3.5
Master Aud Io	-3.5	-3.5	-3.5	-3.5
20M RP Video	-3.5	-3.5	-3.5	-3.5
Master Aud Io	-3.5	-3.5	-3.5	-3.5
20M FB Video	-3.5	-3.5	-3.5	-3.5
Master Aud Io	-3.5	-3.5	-3.5	-3.5
20M RP Video	-3.5	-3.5	-3.5	-3.5
Master Aud Io	-3.5	-3.5	-3.5	-3.5
20M FB Video	-3.5	-3.5	-3.5	-3.5
Master Aud Io	-3.5	-3.5	-3.5	-3.5
20M RP Video	-3.5	-3.5	-3.5	-3.5
Master Aud Io	-3.5	-3.5	-3.5	-3.5
20M FB Video	-3.5	-3.5	-3.5	-3.5
Master Aud Io	-3.5	-3.5	-3.5	-3.5
20M RP Video	-3.5	-3.5	-3.5	-3.5
Master Aud Io	-3.5	-3.5	-3.5	-3.5



Its

Insight Technical Support
 20 Whiting Street
 Artarmon NSW 2064
 Phone (61-2) 9436-4555
 Mobile 0418-468-394
 Email insightmail@tpg.com.au

INSIGHT

TECHNICAL SUPPORT



SONY Authorised Service Centre



WHO

Insight is operated by Ray Purnell.

Ray has had extensive experience in the broadcast and professional television industry continuously over the past twenty five years. After his initial traineeship in electronics engineering achieving Honours, and working for a Sydney production house, he joined Sony Broadcast. There he was given specific training in the Sony B & P product range with extensive training in the US, UK, Japan and in Sydney and Melbourne. He worked on most products in the Sony B & P range whilst there.

WHAT

Insight Technical Support was formed in 1990 as an independent solution for facilities needing broadcast and professional technical support.

Insight is an Authorised Service Centre for Sony and Panasonic professional and broadcast video recorders, cameras and monitors, including formats such as Digital Betacam, HDCam, HDCam SR, XDCam, SX, IMX, DVcam; DVCPRO, DVCPROHD, Varicam, P2 and HD-D5. Insight is involved with Sony's and Panasonic's on-going certification scheme, in order to maintain excellence in repair standards.

With our extensive experience and modern well equipped workshop, we can offer you cost effective, fast and reliable support for your equipment.

Insight has many well known and respected customers and would welcome you to become one of them.


WHERE

We are located 1 minute from the Reserve Road exit off the Gore Hill Freeway, or turn from the Pacific Highway into Whiting Street.

We are located in the VA Hire building.

Building access at 20 Whiting Street or at rear in Curry Lane.

Phone from the car park for carry in service.



Map Courtesy of Google Maps